



Report No.: ECT20230714045C

锂电池

符合特殊规定 188

海运运输条件鉴别报告书

Identification and Classification Report for Sea Transport of Goods

本报告本年度有效
有效期至 2024 年 12 月 31 日

委托单位:

东莞市全一能源有限公司

Client

Dongguan Quanyi Energy Co., Ltd.

委托方地址:

东莞市常平镇东深路 31 号

Add. Of Client

31 Dongshen Road, Changping Town, Dongguan City,
China

物品名称:

聚合物锂离子电芯 QY 400909 3.7V 28mAh 0.1036Wh

Name of Goods

Polymer Li-ion Cell QY 400909 3.7V 28mAh 0.1036Wh

签发日期:

2023.12.07

Issued Date:

深圳市卓越检测技术有限公司

Shenzhen ECT Testing Technology Co.,Ltd



报告书使用约定

Terms of the Using of the Report

1. 本公司依据委托人(托运人或其代理人)提供的物品及其运输信息, 确定货物的运输条件并出具此报告书。
The report is issued by ECT according to the information of the goods and the information of its shipping provided by the applicant (shipper or his agent).
2. 依据鉴别的需要, 本公司要求委托人提供真实、完整的货物样品及资料。
According to the demanded of identification and classification, ECT requires the applicant to provide true and exact sample and data of the cargo.
3. 委托人保证申报的物品/或提供的样品与交运的货物是同一种物质。
The applicant guarantees that the declared goods and/or the sample who provides should be identical with the contents of cargo that is to be transported.
4. 本公司仅对样品的鉴别结果负责。
ECT is only responsible for the identification and classification of the sample provided by the applicant.
5. 本报告书经主检员、审批人和批准人签字并加盖本公司印章后生效。
This report will be effective only after is signed by inspector, checker and approver, and stamped by ECT.
6. 未经本公司书面批准, 不得部分复制本报告。
The partially duplicating of this report is prohibited without the written approval of ECT.
7. 私自转让、复制、盗用、冒用、涂改、或以任何媒体形式篡改的报告书无效。
The report is invalid when anything of the following happens-illegal transfer, reproduce, embezzlement, obliterate, modification or tampering in any media form.
8. 报告书仅在本年度有效。
This report is only valid within the year.

鉴别目的 Identification Purpose	是否属于海运危险品 Dangerous Goods or not restricted	鉴别日期 Identification Date	2023.12.07
鉴别依据 Identification Criteria	IMDG CODE(Amdt 41-22)		
委托单位 Client	东莞市全一能源有限公司 Dongguan Quanyi Energy Co., Ltd.		
地址 Client Address	东莞市常平镇东深路 31 号 31 Dongshen Road, Changping Town, Dongguan City, China		
制造商 Manufacturer	东莞市全一能源有限公司 Dongguan Quanyi Energy Co., Ltd.		
地址 Manufacturer Address	东莞市常平镇东深路 31 号 31 Dongshen Road, Changping Town, Dongguan City, China		
物品名称 Name of Goods	聚合物锂离子电池 QY 400909 3.7V 28mAh 0.1036Wh Polymer Li-ion Cell QY 400909 3.7V 28mAh 0.1036Wh		
物品信息 Nature of the goods	型号规格: Model/Type	QY 400909 3.7V 28mAh 0.1036Wh 4*4*9(mm)	





	外观 Appearance	棱柱形 Prismatic
	每包装件电池/电芯数目 Net number of batteries/cell per package	4000 PCS
	UN38.3 报告编号 UN38.3 report No.	ECT20230714045A
	1.2m 跌落测试报告为 1.2m drop test report No.	ECT20230714045B
鉴别结论 Conclusions	非限制性 Not subject these Regulations 根据特殊规定 188, 该物品不受 IMO IMDG CODE 限制。 The article is not restricted to IMO IMDG CODE according to special provision 188	
备注 Comment	每一电池必须做好防短路措施, 并装入坚固外包装内。 Each single battery must be packed in such a way as to prevent short circuits normal conditions and packed in strong outer packaging.	
主检员: <i>lee.yuan</i> 审核人: <i>Eddie.Shi</i> 批准人: <i>Eric.Ren</i> Appraiser checked Approved ECT 印章 Seal of ECT		
鉴别项目名称 Item	检查结果 Inspection Result	
该电池额定瓦特小时数为 0.1036Wh Watt-hour rating of the battery is 0.1036Wh	≤100 Wh	
该电池已通过 UN38.3 测试 Each battery is of a type proved to meet the Requirements of each test in the UN MANUAL OF TESTING AND CRITERIA, Part III, sub-section 38.3	符合 Conform	
电池按照规定的质量管理体系进行制造 Batteries be manufactured under a quality management programmer.	符合 Conform	
该锂电池不属于召回电池, 不属于废弃和回收电池 The lithium batteries don't belong to batteries returned to the manufacturer for safety reasons, are not waste lithium batteries and not lithium cells being shipped for recycling or disposal.	符合 Conform	



<p>通过包装件 1.2 米跌落试验 Each package is capable of withstanding a 1.2m drop test in any orientation</p>	<p>符合 Conform</p>
<p>每个包装件上均有锂电池操作标签。 每票货物均有随附文件说明:包装件内装锂离子电池;必须小心操作。如包装件破损,有易燃危险品;包装件破损时应采取的特殊措施,包括必要时的检查和重新包装;应急电话号码。 Each package is labeled with lithium battery handling label. Each consignment is accompanied with a document with an indication that: The package contains lithium ion batteries; The package must be handled with care, and that a flammability hazard exists if the package is damaged; Special procedures should be followed in the event the package is damaged, to include inspection and repacking if necessary; and A telephone number for additional information</p>	<p>符合 Conform</p>



THE PHOTO OF SAMPLE 样品图片



End of report